FOR THE MONTH OF Oct-2012

Date	Place of Work	No	L	B	D	Qty
01.10.2012	Removal of Debris in Lokanath of Lier House Babanna Layout in W No.12. Tractor No KA-02-Z399	1	3.20	1.50	0.95	4.56
		1	6.50	1.20	0.75	5.85
					Cum	**10.41**
02.10.2012	Removal of Debris in Lokanath of Lier House Babanna Layout in W No.12. Tractor No KA-02-Z399	1	12.10	1.00	1.00	12.10
		1	3.60	0.60	0.60	1.30
		1	2.85	1.00	1.00	2.85
					Cum	**16.25**
03.10.2012	Removal of Debris in Lokanath of Lier House Babanna Layout in W No.12. Tractor No KA-02-Z399	1	13.60	0.90	0.90	11.02
		1	1.65	1.00	1.00	1.65
					Cum	**12.67**
04.10.2012	Removal of Debris in Lokanath of Lier House Babanna Layout in W No.12. Tractor No KA-02-Z399	1	12.65	1.00	1.00	12.65
		2	6.00	1.00	0.70	8.40
					Cum	**21.05**
05.10.2012	Removal of Debris Geleyara Balaga Main road in Ward No.12 Tractor No KA-02-Z399	1	6.50	1.00	0.70	4.55
		2	6.00	1.00	0.70	8.40
					Cum	**12.95**
06.10.2012	Inntensive Cleaning	Not Susceptible				
07.10.2012	Removal of Debris Geleyara Balaga Main road in Ward No.12 Tractor No KA-02-Z399	1	6.50	1.00	0.70	4.55
		2	6.00	1.00	0.70	8.40
					Cum	**12.95**
08.10.2012	Removal of Debris Geleyara Balaga Main road in Ward No.12 Tractor No KA-02-Z399	1	3.20	1.50	0.95	4.56
		1	6.80	1.35	0.85	7.80
					Cum	**12.36**
09.10.2012	Removal of Debris in Deck slab reloaded damaged culverts at abbigere main road in Ward No.12 Tractor No KA-02-Z399	1	6.80	2.10	0.80	11.42
					Cum	**11.42**
10.10.2012	Removal of Debris in Deck slab reloaded damaged culverts at Medarahalli main road in Ward No.12 Tractor No KA-02-Z399	1	10.00	0.90	0.75	6.75
		1	8.00	0.90	0.60	4.32
		1	14.00	0.90	0.30	3.78
					Cum	**14.85**
11.10.2012	Removal of Debris in Deck slab reloaded damaged culverts at Geleyara Balaga main road in Ward No.12 Tractor No KA-02-Z399	2	3.00	1.50	0.90	8.10
		1	3.00	1.50	0.75	3.38
					Cum	**11.48**

Scanned by CamScanner

12.10.2012	Removal of Debris in Deck slab reloaded damaged culverts at Raghavendra Layout main road in Ward No.12 Tractor No KA-02-Z399	1	3.60	1.00	1.00	3.60
		2	6.30	0.90	0.60	6.80
		1	2.00	1.00	1.00	2.00
					Cum	**12.40**
13.10.2012	Inntensive Cleaning	Not Susceptible				
14.10.2012	Holiday					
15.10.2012	Removal of Debris in Deck slab reloaded damaged culverts at Vijayalakshmi Layout main road in Ward No.12 Tractor No KA-02-Z399	1	12.65	0.60	0.60	4.55
		2	13.00	1.00	0.90	23.40
					Cum	**27.95**
16.10.2012	Removal of Debris in Deck slab reloaded damaged culverts at Shettyhalli and Surrounding area main road in Ward No.12 Tractor No KA-02-Z399	1	6.80	1.35	0.85	7.80
		1	7.30	1.00	1.00	7.30
		1	3.60	0.60	0.60	1.30
					Cum	**16.40**
17.10.2012	Removal of Debris in Deck slab reloaded damaged culverts at Shettyhalli and Surrounding area main road in Ward No.12 Tractor No KA-02-Z399	1	10.00	1.10	0.75	8.25
		1	11.60	0.75	0.30	2.61
					Cum	**10.86**
18.10.2012	Removal of Debris in Deck slab reloded damaged culverts at Geleyarabalaga and Surrounding area main road in Ward No.12 Tractor No KA-02-Z399	1	12.00	1.90	1.00	22.80
		1	3.65	0.60	0.30	0.66
		1	1.20	1.00	1.00	1.20
		1	6.90	0.65	0.20	0.90
					Cum	**25.55**
19.10.2012	Removal of Debris in Deck slab reloded damaged culverts at Geleyarabalaga and Surrounding area main road in Ward No.12 Tractor No KA-02-Z399	1	11.60	0.75	0.35	3.05
		1	7.60	0.60	0.35	1.60
		1	12.35	1.10	0.75	10.19
		1	6.30	0.65	0.20	0.82
					Cum	**15.65**
20.10.2012	Intensive Cleaning	Not Susceptible				
21.10.2012	Removal of Debris in Deck slab reloded damaged culverts at A V R Layout and Surrounding area main road in Ward No.12 Tractor No KA-02-Z399	1	12.35	1.10	0.75	10.19
		1	3.60	1.00	1.00	3.60
		1	2.65	0.90	0.90	2.15
					Cum	**15.94**

Scanned by CamScanner

22.10.2012	Removal of Debris in Deck slab reloded damaged culverts at Venkateshwara Layout and Surrounding area main road in Ward No.12 Tractor No KA-02-Z399	1	3.60	0.90	0.60	1.94
		1	12.60	0.35	0.10	0.44
		3	3.65	1.00	1.00	10.95
					Cum	**13.34**
23.10.2012	Removal of Debris in Deck slab reloded damaged culverts at Vijayalakshmi Layout and Surrounding area main road in Ward No.12 Tractor No KA-02-Z399	1	12.60	0.65	0.35	2.87
		2	7.65	0.50	0.25	1.91
		1	12.30	1.00	1.00	12.30
					Cum	**17.08**
24.10.2012	Removal of Debris in 2nd Main and Surrounding area main road in Ward No.12 Tractor No KA-02-Z399	1	8.60	0.90	0.65	5.03
		1	13.60	0.75	0.60	6.12
		1	6.30	0.60	0.50	1.89
					Cum	**13.04**
25.10.2012	Removal of Debris in 2nd Main and RR College Surrounding area main road in Ward No.12 Tractor No KA-02-Z399	1	2.85	1.00	1.00	2.85
		2	13.60	0.75	0.60	12.24
		1	2.66	1.00	1.00	2.66
					Cum	**17.75**
26.10.2012	Removal of Debris in 2nd Main and RR College Surrounding area main road in Ward No.12 Tractor No KA-02-Z399	1	9.65	0.90	0.90	7.82
		1	10.65	0.75	0.30	2.40
					Cum	**10.21**
27.10.2012	Removal of Debrisoad Surrounding area main road in Ward No.12 Tractor No KA-02-Z399	1	10.00	0.90	0.60	5.40
		1	8.00	1.20	0.40	3.84
					Cum	**9.24**
28.10.2012	Removal of Debris in 2nd Main and RR College Surrounding area main road in Ward No.12 Tractor No KA-02-Z399	1	9.40	1.20	0.75	8.46
		1	3.00	1.00	1.00	3.00
					Cum	**11.46**
29.10.2012	Removal of Debris in 2nd Main and Gopalappa House in Abbigere Surrounding area main road in Ward No.12 Tractor No KA-02-Z399	1	5.00	1.30	0.90	5.85
		1	3.00	1.20	0.60	2.16
		1	10.00	0.90	0.60	5.40
					Cum	**13.41**
		1	6.50	1.20	0.75	5.85

Scanned by CamScanner

30.10.2012	Removal of Debris in Park near Govt Hospital in Abbigere Surrounding area main road in Ward No.12 Tractor No KA-02-Z399	1	3.20	1.00	1.00	3.20
		1	16.30	0.55	0.35	3.14
		1	3.85	0.55	0.25	0.53
					Cum	**12.72**
31.10.2012	Removal of Debris in Park near Govt Hospital in AbbigereSurrounding area main road in Ward No.12 Tractor No KA-02-Z399	2	9.85	1.00	0.60	11.82
					Cum	**11.82**

Certificate:-1) Certified that contractor has done the work Satisfactory.

2) Certified that contractor has removed all debris from work spot.

Ravi.N.K.
- AEW.12

ಸಹಾಯಕ ~~ಕಾರ್ಯಪಾಲಕ~~ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್ ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Scanned by CamScanner

FOR THE MONTH OF Jan-2013

Date	Place of Work	No	L	B	D	Qty
01.01.2013	Removal of Debris in in Kammagondanahalli Main Road and 7th cross Sourrending area in W No.12. Tractor No KA-02-Z399	1	6.50	1.20	0.75	5.85
		1	3.20	1.50	0.75	3.60
					Cum	**9.45**
02.01.2013	Removal of Debris in Culverts drains in 1st Cross and Surrounding Area in AVR Layout in W No.12. Tractor No KA-02-Z399	1	9.40	1.20	0.75	8.46
					Cum	**8.46**
03.01.2013	Removal of Debris in Culverts drains in 1st Cross and Surrounding Area in AVR Layout in W No.12. Tractor No KA-02-Z399	1	17.65	1.00	1.00	17.65
					Cum	**17.65**
04.01.2013	Removal of Debris in Culverts drains in 1st Cross and Surrounding Area in AVR Layout in W No.12. Tractor No KA-02-Z399	1	17.65	1.00	1.00	17.65
					Cum	**17.65**
05.01.2013	Inntensive Cleaning	Not Susceptible				
06.01.2013	Removal of Debris in Culverts drains in 1st Cross and Surrounding Area in Medarahalli Railway Gate in W No.12. Tractor No KA-02-Z399	1	6.80	1.35	0.85	7.80
		1	8.65	1.00	1.00	8.65
					Cum	**16.45**
07.01.2013	Removal of Debris in Culverts drains in 1st Cross and Surrounding Area in Medarahalli Railway Gate in W No.12. Tractor No KA-02-Z399	1	10.30	1.35	0.85	11.82
					Cum	**11.82**
08.01.2013	Removal of Debris in Culverts drains in 1st Cross and Surrounding Area in Shettyhalli Village in W No.12. Tractor No KA-02-Z399	1	7.90	1.40	0.90	9.95
		1	2.10	1.00	1.00	2.10
					Cum	**12.05**
09.01.2013	Removal of Debris in Culverts drains in 1st Cross and Surrounding Area in Shettyhalli Village in W No.12. Tractor No KA-02-Z399	1	9.30	1.60	0.85	12.65
					Cum	**12.65**

Scanned by CamScanner

10.01.2013	Removal of Debris in Culverts drains in 1st Cross and Surrounding Area in Medarahalli Railway Gate in W No.12. Tractor No KA-02-Z399	1	8.90	1.40	0.90	11.21
		1	3.65	0.90	0.90	2.96
					Cum	**14.17**
11.01.2013	Removal of Debris in near Venkatesh House in KG Halli and Surrounding Area in W No.12. Tractor No KA-02-Z399	1	18.39	1.20	1.00	21.96
					Cum	**21.96**
12.01.2013	Inntensive Cleaning	Not Susceptible				
13.01.2013	Removal of Debris in Janatha Colony and Shettyhalli main road and Abbigere in W No.12. Tractor No KA-02-Z399	1	13.65	1.00	1.00	13.65
					Cum	**13.65**
14.01.2013	Removal of Debris in near Venkatesh House in KG Halli and Surrounding Area in W No.12. Tractor No KA-02-Z399	1	19.90	1.50	0.85	13.90
					Cum	**13.90**
15.01.2013	Removal of Debris in near Venkatesh House in KG Halli and Surrounding Area in W No.12. Tractor No KA-02-Z399	1	9.00	1.20	0.75	8.10
		1	3.65	1.20	0.90	3.94
					Cum	**12.04**
16.01.2013	Removal of Debris in near Venkatesh House in KG Halli and Surrounding Area in W No.12. Tractor No KA-02-Z399	1	9.70	1.50	0.85	12.37
					Cum	**12.37**
17.01.2013	Removal of Debris in Kempegowda Garden and Surrounding Abbigere in W No.12. Tractor No KA-02-Z399	1	18.62	1.10	1.00	20.48
					Cum	**20.48**
18.01.2013	Removal of Debris in Geleyarabalaga in Main Road Surrounding in Ward No.12 Tractor No KA-02-Z399	1	10.60	1.50	0.85	13.52
					Cum	**13.52**
19.01.2013	Inntensive Cleaning	Not Susceptible				
20.01.2013	Holiday					
21.01.2013	Removal of Debris in near Venkatesh House in KG Halli and Surrounding Area in W No.12	1	9.30	1.60	0.85	12.65

Scanned by CamScanner

	Tractor No KA-02-/3499					
					Cum	
22 01 2013	Removal of Debris in culverts drains in [illegible] and Surrounding area in Shanthala [illegible] Ward No 12 Tractor No KA-02-/3499				Cum	
23 01 2013	Removal of Debris in Kempegowda Circle cross and surrounding Attigere Area in Ward No 12 Tractor No KA-02-/3499				Cum	
24 01 2013	Removal of Debris in culverts drains in [illegible] cross and Surrounding area in Shanthala [illegible] in Ward No 12 Tractor No KA-02-/3499				Cum	
25 01 2013	Removal of Debris in culverts drains in [illegible] and Surrounding area in Shanthala [illegible] Ward No 12 Tractor No KA-02-/3499				Cum	
26 01 2013	Intensive Cleanse					
27 01 2013	Removal of Debris in culverts drains in [illegible] and Surrounding area in Rajeevgandhi Layout [illegible] Ward No 12 Tractor No KA-02-/3499				Cum	
28 01 2013	Removal of Debris in culverts drains in [illegible] and Surrounding area in K G Halli in Ward No 12 Tractor No KA-02-/3499				Cum	
29 01 2013	Removal of Debris in culverts drains in [illegible] and Surrounding area in ABV Layout in Ward No 12 Tractor No KA-02-/3499				Cum	
30 01 2013	Removal of Debris in culverts drains in [illegible] and Surrounding area in Medarahalli in Ward No 12 Tractor No KA-02-/3499				Cum	
31 01 2013	Removal of Debris in culverts drains in [illegible] and Surrounding area in Venkateshwara [illegible]					

Certificate:- 1) certified that contractor has done the above Sanitation work

2) certified that Contractor has removed all debris from above work

Scanned by CamScanner

FOR THE MONTH OF May-2013

Date	Place of Work	No	L	B	D	Qty
01.05.2013	Holiday					
02.05.2013	Removal of Debris in and Refixing slabs in Ragavendra Layout main road Kammagondanahalli in W No.12. Tractor No KA-02-Z399	1	9.00	1.75	0.80	12.60
		1	12.00	1.00	0.65	7.80
		1	10.00	0.90	1.00	9.00
					Cum	**29.40**
03.05.2013	Removal of Debris in and Refixing slabs in Shettyhalli main road in W No.12. Tractor No KA-02-Z399	1	7.90	1.40	0.90	9.95
		1	10.00	0.60	0.60	3.60
					Cum	**13.55**
04.05.2013	Inntensive Cleaning	Not Susceptible				
05.05.2013	Removal of Debris in AVR Layout main road in W No.12. Tractor No KA-02-Z399	2	2.00	1.60	0.90	5.76
		1	6.00	1.30	0.90	7.02
					Cum	**12.78**
06.05.2013	Removal of Debris in Medarahalli Layout main road in W No.12. Tractor No KA-02-Z399	1	8.00	0.90	0.60	4.32
		1	7.65	1.00	1.00	7.65
		1	6.00	0.65	0.75	2.93
		1	8.00	1.30	0.60	6.24
					Cum	**21.14**
07.05.2013	Removal of Debris in RR Layout Mazid road in W No.12. Tractor No KA-02-Z399	1	7.65	0.90	0.60	4.13
		1	9.20	0.80	0.80	5.89
		1	12.00	0.60	0.45	3.24
					Cum	**13.26**
08.05.2013	Removal of Debris in 6th Main Babanna Layout in W No.12. Tractor No KA-02-Z399	1	9.00	1.60	1.00	14.40
		1	6.00	1.00	1.00	6.00
		1	5.00	1.50	0.90	6.75
					Cum	**27.15**
	Removal of Debris in 6th Main Babanna Layout	1	10.60	0.60	0.30	1.91
		1	9.00	1.30	1.00	11.70

Scanned by CamScanner

9.05.2013	in W No.12. Tractor No KA-02-Z399	1	11.00	1.00	0.90	9.90
		1	10.00	0.90	0.45	4.05
					Cum	**27.56**
10.05.2013	Removal of Debris in 6th Main Babanna Layout in W No.12. Tractor No KA-02-Z399	1	11.00	0.90	0.75	7.43
		1	15.00	1.00	0.60	9.00
					Cum	**16.43**
11.05.2013	Inntensive Cleaning	Not Susceptible				
12.05.2013	Removal of Debris Chikkasandra Colony SWD Drain and Surrounding area in W No.12. Tractor No KA-02-Z399	1	6.80	1.35	0.85	7.80
		1	11.20	0.90	0.60	6.05
					Cum	**13.85**
13.05.2013	Removal of Debris Chikkasandra Colony SWD Drain and Surrounding area in W No.12. Tractor No KA-02-Z399	1	10.00	0.90	0.45	4.05
		1	3.20	1.50	0.95	4.56
		1	3.00	1.00	0.60	1.80
		1	2.00	0.90	0.90	1.62
					Cum	**12.03**
14.05.2013	Removal of Debris Chikkasandra Colony SWD Drain and Surrounding area in W No.12. Tractor No KA-02-Z399	1	10.20	1.60	0.85	13.87
		1	9.00	1.00	0.90	8.10
		1	10.00	1.00	0.65	6.50
					Cum	**28.47**
15.05.2013	Removal of Debris Chikkasandra Colony SWD Drain and Surrounding area in W No.12. Tractor No KA-02-Z399	2	11.60	1.20	1.00	27.84
		1	9.30	1.60	0.85	12.65
					Cum	**40.49**
16.05.2013	Removal of Debris KG Halli 11th main road & Cross roads near SWD Drain slab Removing and cleaning in W No.12. Tractor No KA-02-Z399	1	9.60	0.90	0.75	6.48
		1	11.00	1.00	0.60	6.60
		1	10.00	1.20	0.75	9.00
					Cum	**22.08**
17.05.2013	Removal of Debris KG Halli 11th main road & Cross roads near SWD Drain slab Removing and cleaning in W No.12. Tractor No KA-02-Z399	1	9.30	1.60	0.85	12.65
		1	12.00	0.90	0.60	6.48
		1	7.00	1.00	0.60	4.20
					Cum	**23.33**
18.05.2013	Inntensive Cleaning	Not Susceptible				
19.05.2013	Removal of Debris in near Venkatesh House in KG Halli and Surrounding Area in W No.12. Tractor No KA-02-Z399	1	9.40	1.40	0.75	9.87
		1	12.00	1.60	1.20	23.04
					Cum	**32.91**
20.05.2013	Removal of Debris and Refixing slabs in Abbigere main road and 3rd cross in W No.12. Tractor No KA-02-Z399	1	12.00	1.35	0.85	13.77
					Cum	**13.77**
21.05.2013	Removal of Debris and Refixing slabs in Abbigere main road and 3rd cross in W No.12.	1	10.40	1.20	0.75	9.36
		1	12.00	1.00	0.60	7.20

Scanned by CamScanner

	Tractor No KA-02-/399				Cum	16.56
22.05.2013	Removal of Debris and Refixing slabs in Abbigere main road and 3rd cross in W No.12. Tractor No KA-02-Z399	1	10.20	1.40	0.90	2.35
		1	9.00	1.20	0.60	6.48
					Cum	19.33
23.05.2013	Removal of Debris main road and cross roads Medarahalli in Ward No.12 Tractor No KA-02-/399	1	12.00	0.60	0.30	2.16
		1	12.00	0.90	0.30	3.24
					Cum	5.40
24.05.2013	Removal of Debris main road and cross roads Medarahalli in Ward No.12 Tractor No KA-02-/399	1	10.40	1.20	0.75	9.36
		1	9.60	0.95	0.75	6.84
					Cum	16.21
25.05.2013	Inntensive Cleaning	Not Suseatable				
26.05.2013	Removal of Debris in Babanna Layout Archakara House road and Surrounding cross roads in Ward No.12 Tractor No KA-02-Z399	1	6.80	1.35	0.85	7.80
		1	11.00	1.20	0.85	11.22
					Cum	19.02
27.05.2013	Removal of Debris in Babanna Layout Archakara House road and Surrounding cross roads in Ward No.12 Tractor No KA-02-Z399	1	9.40	1.40	0.75	9.87
		1	11.00	0.75	0.45	3.71
					Cum	13.58
28.05.2013	Removal of Debris in Babanna Layout Archakara House road and Surrounding cross roads in Ward No.12 Tractor No KA-02-/399	1	9.70	1.50	0.85	12.37
		1	10.00	0.60	0.30	1.80
					Cum	14.17
29.05.2013	Removal of Debris AYR Layout near Gopal House Surrounding in Ward No.12 Tractor No KA-02-/399	1	10.00	1.10	0.60	6.60
		1	4.00	0.90	0.60	2.16
		1	6.00	0.60	0.20	0.72
					Cum	9.48
30.05.2013	Removal of Debris Medarahalli near Railway Gate Palya near Mazid road in Ward No.12 Tractor No KA-02-/399	1	12.65	1.20	0.90	13.66
		1	10.00	0.90	0.45	4.05
					Cum	17.71
31.05.2013	Removal of Debris Medarahalli near Railway Gate Palya near Mazid road in Ward No.12 Tractor No KA-02-/399	1	12.65	1.20	0.90	13.66
		1	10.00	0.90	0.45	4.05
					Cum	17.71

Certificate:-

1) Certified that contractor has done the work satisfactory

2) certified that Contractor has removed all debris from work spot

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶಿವಾಜಿನಗರ ಉಪವಿಭಾಗ, ಬೃಹತ್ ಬೆಂಗಳೂರು ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Javi.N.K,
- AEW-12

Scanned by CamScanner

FOR THE MONTH OF Aug-2013

Date	Place of Work	No	L	B	D	Qty
01.08.2013	Removal of Debris in Culverts drains in 1st Cross and Surrounding Area in Medarahalli Railway Gate in W No.12. Tractor No KA-02-Z399	1	10.30	1.35	0.85	11.82
					Cum	11.82
02.08.2013	Removal of Debris in Culverts drains in 1st Cross and Surrounding Area in Shettyhalli Village in W No.12.	1	7.90	1.40	0.90	9.95
		1	2.10	1.00	1.00	2.10
					Cum	12.05
03.08.2013	Inntensive Cleaning	Not Suscatable				
04.08.2013	Removal of Debris in culverts drains in 3rd cross and Surrounding area in K G Halli in Ward No.12 Tractor No KA-02-Z399	1	7.90	1.40	0.90	9.95
		2	1.00	0.90	0.90	1.62
					Cum	11.57
05.08.2013	Removal of Debris in culverts drains in 7th cross and Surrounding area in ABV Layout in Ward No.12 Tractor No KA-02-Z399	1	9.00	1.20	0.75	8.10
					Cum	8.10
06.08.2013	Removal of Debris in culverts drains in 5th cross and Surrounding area in Medarahalli in Ward No.12 Tractor No KA-02-Z399	1	11.10	0.55	0.45	2.75
		1	12.10	1.65	0.80	15.97
					Cum	18.72
07.08.2013	Removal of Debris in culverts drains in 5th cross and Surrounding area inVenkateshwara Layout in Ward No.12 Tractor No KA-02-Z399	1	10.20	1.80	0.95	17.44
					Cum	17.44
08.08.2013	Removal of Debris in culverts drains in 10th cross and Surrounding area in AVB Layout in Ward No.12 Tractor No KA-02-Z399	1	10.40	1.20	0.75	9.36
		1	12.10	0.80	0.65	6.29
					Cum	15.65
09.08.2013	Removal of Debris in culverts drains in 11th cross and Surrounding area in Shettyhalli in Ward No.12 Tractor No KA-02-Z399	1	9.00	1.20	0.75	8.10
		1	3.65	1.00	1.00	3.65
					Cum	11.75
10.08.2013	Inntensive Cleaning	Not Suscatable				

Scanned by CamScanner

22.08.2013	Removal of Debris in culverts drains in Ist cross and Surrounding area in Abbigere Village in Ward No 12 Tractor No KA-02-Z399	1	7.90	1.40	0.90	9.97
		1	6.30	0.90	0.90	5.1
					Cum	15.15
23.08.2013	Removal of Debris in Babanna Layout Archakara House road and Surrounding cross roads in Ward No 12 Tractor No KA-02-Z399	1	9.70	1.50	0.85	12.37
		1	10.00	0.60	0.30	1.8
					Cum	14.17
24.08.2013	Inntensive Cleaning	Not Susceptible				
25.08.2013	Holiday					
26.08.2013	Removal of Debris AYR Layout near Gopal House Surrounding in Ward No 12 Tractor No KA-02-Z399	1	10.00	1.10	0.60	6.6
		1	4.00	0.90	0.60	2.4
		1	6.00	0.60	0.20	0.72
					Cum	9.48
27.08.2013	Removal of Debris Medarahalli near Railway Gate Palya near Mazid road in Ward No 12 Tractor No KA-02-Z399	1	12.65	1.20	0.90	13.65
		1	10.00	0.90	0.45	4.5
					Cum	17.71
28.08.2013	Removal of Debris Medarahalli near Railway Gate Palya near Mazid road in Ward No 12 Tractor No KA-02-Z399	1	12.65	1.20	0.90	13.65
		1	10.00	0.90	0.45	4.5
					Cum	17.71
29.08.2013	Removal of Debris Geleyara Balaga Main road in Ward No 12 Tractor No KA-02-Z399	1	3.20	1.50	0.95	4.56
		1	6.80	1.35	0.85	7.80
					Cum	12.36
30.08.2013	Removal of Debris in Deck slab reloaded damaged culverts at abbigere main road in Ward No.12 Tractor No KA-02-Z399	1	6.80	2.10	0.80	12
					Cum	11.42
31.08.2013	Inntensive Cleaning	Not Susceptable				

Certificate:-

1) certified that Contractor hay done the work satisfactory.

2) certified that contractor hay removed all debris from work spot

3) Certified that there is no due work from contractor side

Sd/- N.K.
AE Work

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Scanned by CamScanner